

SB3 Coatings

Recommended Maintenance

WASHING

- ◆ For best results wash on a bi-weekly basis to avoid excessive contamination build up.
- ◆ Avoid washing in direct sunlight to avoid streaking and water spotting.
- ◆ Wash top surfaces first then move to lower areas
- ◆ Use separate bucket, soap and micro fiber for wheels.

DRYING

- ◆ Always dry completely and never leave to “air” dry. Tap water contains minerals that may leave deposits creating water spots.
- ◆ Using a powerful cordless leaf blower is an affective way to remove water from cracks and door jams.
- ◆ You may also use quality microfiber towels and avoid aggressive wiping, allowing the material to glide across the surface And absorb the water.

SPOT REMOVAL

- ◆ Never use aggressive products to polish the coating or remove surface contamination.
- ◆ Never use excessive force to remove spots.
- ◆ Bird droppings, tar, sap, etc. should be removed as soon as possible to avoid staining or hardening on the coating. Any staining left behind from the bird droppings will break down over a few days without affecting the coating.

For assistance additional questions or concerns please feel free to contact your local SB3 Coatings Agent or SB3 Coatings directly. Thank you for joining the SB3 Army of Clients!

